UNITED STATES DEPARTMENT OF THE INTERIOR Heritage Conservation and Recreation Service
Office of Archeology and Historic Preservation
Washington D.C. 20243

B-3866 MAGI # Q438662504



Keeper of the National Register

## HISTORIC PRESERVATION CERTIFICATION APPLICATION - PART 1

(Pursuant to the Tax Reform Act of 1976)

nt should read the instructions carefully before completing application. No Certification may be made unless a completed application form has

Instructions: Applicant should read the instruction been received (P.L. 94-455). Use typewriter or print side or a separate plain sheet of paper clearly ind ate State Historic Preservation Officer at any time	t clearly in dark ink to complete th icating the owner's name and ma se during the year, and may be se	e application form. If additional space is: lling address. Part 1 of this application m int separately or with Part 2.	ay be completed and sent to the appropri
PART 1 EVALUATION OF SIG	NIFICANCE		
Franklin	Center		
1. NAME OF PROPERTY: FI dikiti			
1. NAME OF PROPERTY:  Address of property Street 406 West		Maryland	21201
City_Baltimore, Co	Seton Hill	(National Register;	21201 9/30/75; Baltimore City
Name of historic district in which property if	Historic I	District; 7/15/68 & 8/	14/79
2 DESCRIPTION OF PHYSICAL APPEARANCE c - three architecturally turally significant earl altered continually from	their date of cor	which date from the difications. The indiversal distruction and within	idual structures were the last decade suffered
'midings are historica	lly and architectureuse of these but toric district whi persons.	ildings will preserve le providing specializ	District because the development of the the continuity of the ced, barrier-free housing (if known) late 19th c - mid 20th c
Name Accessible Housing Accessible Housing Accessible Street 518 N. Charles St.	Associates, Inc. c	/o Multi-Family Housin	
Street Baltimore		State_	MD Zip Code 21201
City Area Co	de_ (301) 659-6966		
the interest of This	provided is, to the best of my kn	owledge correct and that I am owner of	the property described above
Signature Form prepared by:	TILET TO	lsemer, Catzen and Ass Baltimore, MD 21202	sociates. Inc.
		- /	
For office use only  The structure described above is included w	ithin the boundaries of the Nation	al Register historic district and Fcontrib	utes 🗆 does not contribute to the character of
the district.	- most National Benister Criteria	for Evaluation (36 CFR 60.6) and 🗆 will I	likely 🗆 will not be nominated to the National
Register in accord with the Department of t	the interior processores tes		ISS CER FOR The It likely The III not be nom
The structure is located in a district which ☐ nated to the National Register in accord with	appears   does not appear to mee Department of the Interior proced	ures (36 CFR 60), and $\square$ appears $\square$ does n	(36 CFR 60.6). will likely will not be nome of appear to contribute to the character of sales of the character o
Signature State Pristoric Preservation Office			
and an 167 of the Internal Hevenue Code	01 1354		6 CFR 67) and, if subject to depreciation unde
is hereby certified a historic structure     does not contribute to the character of t	he historic district and does not t	ment certification as a historic structure	Reasons given on the attached shee!

## HISTORIC PRESERVATION CERTIFICATION APPLICATION - Part I

Description of Physical Appearance-cont.


exposure. The rehabilitation plans preserve the architecturally distinct facades and retain the appearance of three individual buildings while linking them into one structure.

404 West Franklin was an earlier 19th century flemish bond brick structure with later 19th and 20th century modifications. The building was four stories high and three bays wide. The fourth story, the cornice, and the flat roof, were later 19th century additions. The first floor has been drastically altered and most recently comprised concrete blocks where a storefront had been. There were remnants of a late 19th century storefront transom and cornice. The second thru fourth floors comprised rectangular window openings with splayed stepped stone lintels. The window openings were boarded or exposed and a portion of the roof was missing. Because of the advanced state of decay and the severe deterioration of the facade materials, the structure was dismantled and will be reconstructed of brick over block. The facade will conform to the design of the previous one in scale, proportion and detail. brick and the design of the window openings will match the originals as closely as possible. The splayed stepped lintels will be salvaged and reinstalled. The cornice will also be reconstructed of wood along the original lines. The first floor design will restore the structure, in part, to its original residential appearance. first floor will comprise three one over one bronze-aluminum awning windows with a fixed transom, brick sills, and rectangular concrete lintels. The windows will have decorative iron window guards over the lower half. The former storefront transom and cornice area will be indicated by four bands of concrete. The second, third, and fourth floor windows will be one over one bronze-aluminum awning windows. The roof will be a built-up surface over insulation and a metal deck.


404 will be connected to 408 by a recessed four story brick addition with bronze-aluminum sliding windows. The recess will retain the appearance of the original streetscape of separate buildings, while accomplishing the necessity of


joining the structures. 408 West Franklin Street is a three and a half story, four bay wide, late 19th century brick commercial structure with brown stone and molded brick details. some point, the fourth story was removed; the brick was painted; and the commercial storefront was inappropriately rebuilt. The metal cornice above the storefront comprises simple brackets, dentils, and recessed panels. The cornice will be restored. The storefront had been deteriorated and boarded, and the end brick piers had been rebuilt in a careless manner. The first floor is being reconstructed to reflect the former commercial character while accommodating the main entrance to the building and residential units on this floor. The first floor will comprise a brick base below two bronze-aluminum sliding windows with a fixed glass transom over each window; and metal and glass commercial storefront double doors with a single pane sidelight and a fixed transom above the door and sidelight. Decorative iron window guards will be installed across the windows. The walls surfaces will be covered with a buff color stucco. The window openings on the second and third floors are large and rectangular. The openings have been boarded and the original windows are missing. lintels and sills are brown stone and the bricks framing the window openings have a curved profile. There is a brownstone band with dentils between the second and third floors. The end piers project slightly from the facade wall and have molded brick blocks with a foliated pattern recessed which are being preserved. The half story remnant of the fourth floor is being refinished to a completed and useable fourth floor. The second and third floor openings will be preserved and replacement bronzealuminum slider windows with a fixed transom will be installed. The third floor lintels will be constructed of concrete tinted brown to match the brownstone on the building. The reconstructed fourth floor will have bronze-aluminum sliding windows,

B-3866 Franklin Center 404-412 W. Franklin Street



B-3866 Franklin Center 404-412 W. Franklin Street Block 0547B, Lot 002 Baltimore City






404 W FRANKLIM

TRICK NODITICAL



468 W FINERUM



11.8 N FRANKLIN ST

B-3866



